

Mount the Rectifier onto a metal surface for heat dissipation. Connect the terminal marked + to the battery pack negative terminal. Connect the terminal marked - to the negative lead wire going to the lights, or whatever accessory that is being used.
The other two terminals are not used.

© Copyright Nivel LLC

RK