


WHCUNVN001 Universal Wheel Center Spinner Cap Installation




INSTALLATION INSTRUCTIONS

1. Drill a 1/4" hole through the center of the wheel cover. Drill from front to back on the Turbine and Maxam, and from back to front on the SS. This will make it easier to center the hole.
2. Place the Spinner over the 1/4" hole and insert a screw from behind with a Phillips screwdriver
3. Gently snug the screw, DO NOT OVER TIGHTEN!!!

(Not intended to spin, for decorative purposes only)

Copyright© 1997-2010. All Rights Reserved.

WHCUNVN001 Universal Wheel Center Spinner Cap Installation



INSTALLATION INSTRUCTIONS

1. Drill a 1/4" hole through the center of the wheel cover. Drill from front to back on the Turbine and Maxam, and from back to front on the SS. This will make it easier to center the hole.
2. Place the Spinner over the 1/4" hole and insert a screw from behind with a Phillips screwdriver
3. Gently snug the screw, DO NOT OVER TIGHTEN!!!

(Not intended to spin, for decorative purposes only)

Copyright© 1997-2010. All Rights Reserved.