

| Nominal Voltage | 51.2V |
|---------------------|---------------|
| Working Voltage | 43.2V - 58.4V |
| Recommended Voltage | 48.0V - 57.0V |
| Cells | 16 |
| Nominal Capacity | 60Ah |
| Energy | 3,072Wh |
| Reserve @25A | 144 Minutes |
| Self Discharge | 1% Per Month |
| IP Rating | IP65 |
| | |

| CHARGING | | |
|-------------------------|--------------|--|
| Recom. Charging Current | <30A | |
| Max Charging Current | 60A | |
| Bulk/Absorb Voltage | 57.0V | |
| Float Voltage | 54.0V or Off | |
| BMS High Voltage Cutoff | 59.2V | |
| Charging Temp. Range | 34F to 130F | |

| DISCHARGING | | |
|--------------------------|--------------|--|
| Max Continuous Discharge | 180A | |
| Max Discharge 3 Sec | 360A | |
| Max Discharge 30 Sec | 240A | |
| Recom. Voltage Cutoff | 48.0V | |
| BMS Voltage Cutoff | 43.2V | |
| BMS Voltage Recovery | 46.4V | |
| Discharge Temp Range | -10F to 140F | |

| COMMUNICATION | | |
|---------------|-----|--|
| Bluetooth | Yes | |
| CAN | Yes | |




| SAFETY | | |
|-----------------------------------|---------------------|--|
| Charging Freeze Protection | Yes, Under 34F | |
| Pack Over-Voltage | Yes | |
| Cell Balancing | Yes | |
| Pack Under-Voltage | Yes | |
| Cell Under-Voltage | Yes | |
| Cell Over-Temp | Yes | |
| BMS Over-Temp | Yes | |
| Short Circut/Over Current | Yes | |
| Certifications | UN38.3, UL1642 Cell | |

| PHYSICAL | |
|----------------------|------------------------|
| Cell Chemistry | Lithium Iron Phosphate |
| Cell Type | Prismatic |
| Cell Configuration | 1P16S |
| Series Connectable | No |
| Parallel Connectable | Yes, up to 2 |
| Weight | 70 lbs (42.6Kg) |
| Dimension LxWxH | 13.37"X10.18"X11" |
| Terminal Type | M8 Female |
| Shell Type | Powder Coated Steel |
| UN Shipping Class | UN 3480 |











Torque Specs

M8 Terminal Bolts - 6ft/lbs (72 in/lbs)











READ BEFORE INSTALL

USE & CARE



HEAVY TEAM LIFT REQUIRED



HIGH VOLTAGE
HANDLE WITH CARE



DO NOT PRESSURE WASH OR SUBMERGE



CHARGE BATTERY
BEFORE USE

WARNINGS

High Voltage. DO NOT install or service this battery unless you are properly trained.

- Use only with components that have the same voltage and current rating as the battery.
- DO NOT touch or connect to the terminals unless the battery is manually turned off.
- DO NOT open or attempt to service the battery, there are no user serviceable parts inside.

USE & CARE

- Charge the battery daily to ensure it is always fully charged and ready to use.
- Batteries will not charge if the internal battery temperature falls below 34F.
- DO NOT pressure wash, submerge, or use chemical agents to clean your battery.
- Clean the battery using a damp cloth that does not include chemical agents.



For additional product info, user manuals, user guides, and warranty information, please visit https://ecobattery.com/quickstart or scan the QR code.